

RECEIVED
SEP 11 2003

**Attachment ES-1
Waste Site Reclassification Form**

EDMC

Date Submitted: 08/04/03	Operable Unit(s): 100-BC-2	Control Number: 2003-014
Originator: R. A. Carlson	Waste Site ID: 1607-B9 Septic Tank System	Lead Agency: EPA
Phone: 372-9632	Type of Reclassification Action: Rejected <input type="checkbox"/> Closed Out <input type="checkbox"/> Interim Closed Out <input checked="" type="checkbox"/> No Action <input type="checkbox"/>	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed out, interim closed out, or no action and authorizing backfill of the site, if appropriate. Final removal from the National Priorities List of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

Remedial action at this site has been performed in accordance with remedial action objectives and goals established by the U.S. Environmental Protection Agency and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. The selected remedial action involves (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Area of the Hanford Site, and (3) backfilling the site with clean soil to adjacent grade elevations. The excavation and disposal activities have been completed.

Basis for reclassification:

The 1607-B9 Septic Tank System has been remediated to meet the cleanup standards specified in the *Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units*, U.S. Environmental Protection Agency, Region 10, Seattle, Washington. Remedial actions were performed so as to allow rural-residential use and to protect groundwater and the Columbia River. The basis for reclassification is described in detail in the *Cleanup Verification Package for the 1607-B9 Septic Tank System (CVP-2003-00006)*, Bechtel Hanford, Inc., Richland, Washington.

Beth Bilson
DOE-RL Project Manager


Signature

8/22/03
Date

NA
Ecology Project Manager

Signature

Date

Dennis A. Faulk
EPA Project Manager

Signature

Date